



APPROVED	O.G. FIG.
BY	CLASS SUBCLASS
DRAFTSMAN	

36330 24640460



APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		



1. The first step is to identify the problem. This involves understanding the current situation and what needs to be changed.

363230 2464450

APPROVED	O.G. FIG.	
BY	CLASS.	SUBCLASS
DRAFTSMAN		




Fig. 2

PRIOR ART

Fig. 4

APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

825290 24610760




Fig. 5

APPROVED	O.G. FIG.	
BY +	CLASS	SUBCLASS
DRAFTSMAN		




Fig. 6




Fig. 7




Fig. 8

35230-2703450

APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		




Fig. 9




Fig. 10

005230 24640160




Fig. 12





Fig. 11

APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

Fig. 13



36230-2161450

APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		




Fig. 14

APPROVED	O.G. FIG.	
BY +	CLASS	SUBCLASS
DRAFTSMAN		




Fig. 15

665250 27640150